

Index of Photos

Inspection Number 317730378

CBN Holdings Inc



1 of 25

IMG_0795.JPG

Graphic? No

Trade Secret? No

Confidential? No

Worker's comp



2 of 25

IMG_0796.JPG

Graphic? No

Trade Secret? No

Confidential? No

Emergency exit signage



3 of 25

IMG_0797.JPG

Graphic? No

Trade Secret? No

Confidential? No

Exit sign



4 of 25

IMG_0798.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire escape plan posted throughout facility



5 of 25

IMG_0799.JPG

Graphic? No

Trade Secret? No

Confidential? No

Emergency exit signage posted throughout facility



6 of 25

IMG_0800.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire extinguishers available throughout facility



7 of 25

IMG_0801.JPG

Graphic? No

Trade Secret? No

Confidential? No

Exit sign



8 of 25

IMG_0802.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire escape signage posted throughout facility



9 of 25


IMG_0803.JPG

Graphic? No

Trade Secret? No

Confidential? No

Exit door/fire extinguisher



10 of 25

IMG_0804.JPG

Graphic? No

Trade Secret? No

Confidential? No

CO2 system detection report from Jan 2022



11 of 25

IMG_0805.JPG

Graphic? No

Trade Secret? No

Confidential? No

Alarm system inspection records



12 of 25

IMG_0806.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire alarm panel



13 of 25

IMG_0807.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire alarm panel



14 of 25

IMG_0808.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire alarm panel



15 of 25


IMG_0809.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire alarm panel



16 of 25

IMG_0810.JPG

Graphic? No

Trade Secret? No

Confidential? No

Emergency exit and fire escape plan signage



17 of 25


IMG_0811.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire extinguishers available throughout facility



18 of 25

IMG_0812.JPG

Graphic? No

Trade Secret? No

Confidential? No

Emergency exit and fire escape plan signage



19 of 25

IMG_0813.JPG

Graphic? No

Trade Secret? No

Confidential? No

Emergency exit



20 of 25

IMG_0814.JPG

Graphic? No

Trade Secret? No

Confidential? No

Emergency exit- steel cage door open during business hours while employees are at facility, and closed/locked when everyone leaves for the day.



21 of 25

IMG_0815.JPG

Graphic? No

Trade Secret? No

Confidential? No

Emergency exit signage and fire extinguisher



22 of 25

IMG_0816.JPG

Graphic? No

Trade Secret? No

Confidential? No

Padlock used to lock door at night when all employees leave for the day



23 of 25

IMG_0817.JPG

Graphic? No

Trade Secret? No

Confidential? No

Fire sprinkler riser room and fire alarm above



24 of 25

IMG_0818.JPG

Graphic? No

Trade Secret? No

Confidential? No

View of smoke detector in grow room



25 of 25

IMG_0819.JPG

Graphic? No

Trade Secret? No

Confidential? No

Sprinklers throughout facility

